

2009 RETAIL PRICE LIST

Retail Price List – 4/27/09 – Coordinates with 4/27/09 Catalog



The Quality System of PRO-Warrington Footwear is Certified to ISO 9001:2000

Model #	Description	Price U.S. \$	GSA Code
NFPA 1851 – SELECTION, CARE AND MAINTENANCE			
MP-1851DVD	Structural PPE Care and Maintenance DVD Not Subject to Dealer Discounts	\$ 7.57	633-99

NFPA 1851 Educational Classes, Programs, Compliance Aids, Cleaning, Repair and Support Services are Available through the Honeywell Cleaning & Care Facility -- Contact Our Customer Service Department for Details including a Catalog and Retail Price List

STRUCTURAL FIRE FIGHTING BOOTS – NFPA 1971, 2007 Edition

7000	Integrated Boot-to-Pant Boot – <i>Catalog Pages 30 & 31</i>	TBD	633-32
5006	14" Leather/Advance Rip Stop w/Sloped Back – <i>Catalog Pages 32 & 33</i>	\$ 533.17	633-32
4132	14" Leather/Advance Rip Stop w/Shinguard – <i>Catalog Pages 34 & 35</i>	\$ 506.98	633-32
4000	14" Leather/Advance Rip Stop – <i>Catalog Pages 34 & 35</i>	\$ 506.98	633-32
3009	14" All Leather – <i>Catalog Pages 36 & 37</i>	\$ 493.58	633-32
8000 ^{1,2}	14" Leather/Cement Sole – <i>Catalog Pages 38 & 39</i>	\$ 524.97	633-32
3006 ^{1,2}	10" Leather/Defender Lace-Up w/Speed Zipper – <i>Catalog Pages 40 & 41</i>	\$ 555.24	633-32

TECHNICAL RESCUE BOOTS – NFPA 1951, 2007 Edition

6006 ^{1,2}	8" Leather/Advance Rip Stop/Lace-Up – <i>Catalog Page 42</i>	\$ 530.01	633-32
---------------------	--	-----------	--------

STATION/DUTY BOOT – NON NFPA COMPLIANT

3003	8" Station/Duty Leather Lace-Up w/Speed Zipper – <i>Catalog Page 43</i>	\$ 335.62	633-32
------	---	-----------	--------

WILDLAND BOOTS – NFPA 1977, 2005 Edition

3050	8" Leather Lace-Up w/Plain Toe – <i>Catalog Page 44</i>	\$ 286.63	633-32
3051	8" Leather Lace-Up w/Steel Toe – <i>Catalog Page 44</i>	\$ 293.71	633-32
3060	10" Leather Lace-Up w/Logger's Heel – <i>Catalog Page 45</i>	\$ 355.94	633-32

1 = Indicates Multiple Certifications

2 = Indicates Optional Certifications that Must be Requested at Time of Purchase

PRO-Warrington Footwear
for the Fire Service is
Marketed Exclusively
Through:

Honeywell

First Responder Products
(formerly Total Fire Group)

#1 Innovation Court • Dayton, OH 45414
P.O. Box 13616 • Dayton, OH 45413-0616
(937) 264-2662 • Fax (937) 264-2677 • 1-800-688-6148
Website: www.HoneywellFirstResponder.com
E-mail: info@HoneywellFirstResponder.com

Model #	Description	Price U.S. \$	GSA Code
ACCESSORIES			
<i>Catalog Page 46</i>			
3014	Zippers for Boot Model 3003 – fits up to size 9 1/2 (pair)	\$ 33.27	633-32
3015	Zippers for Boot Model 3003 – fits size 10 and up (pair)	\$ 33.27	633-32
3016	Zippers for Boot Model 3006 – fits up to size 10 (pair)	\$ 36.77	633-32
3017	Zippers for Boot Model 3006 – fits from size 10 1/2 and up (pair)	\$ 36.77	633-32
3018	Zippers for Boot Model 6006 (pair), Small, Fits Sizes 4-5 Mens, 4.5-7 Womens	\$ 33.47	633-32
3019	Zippers for Boot Model 6006 (pair), Medium, Fits Sizes 5.5-10 Mens, 7.5-12 Womens	\$ 33.47	633-32
3020	Zippers for Boot Model 6006 (pair), Large, Fits Sizes 10.5-16 Mens	\$ 33.47	633-32
2014	Cord-Loc® Lace Adjusters (package of 2)	\$ 3.12	633-32
2017	PRO Boot Boxes	\$ 4.89	633-32
2019	Component Sales Kit for Structural (NFPA 1971) Boots	\$ 88.54	633-32
2022	Laces – Talson 63" for Models 3003/3050/3051/6006 – Not Fire Resistant (pair)	\$ 3.02	633-32
2020	Laces – Talson 74" for Models 3060/6006 – Not Fire Resistant (pair)	\$ 4.03	633-32
2024	Laces – Kevlar® 63" for Models 3003/3050/3051/6006 (pair)	\$ 8.71	633-32
2021	Laces – Kevlar® 72" for Models 3006/3060/6006 (pair)	\$ 11.05	633-32
2018	Laces – Kevlar® 120" for Model 3060(pair)	\$ 19.95	633-32
3008LPS	Replacement Pull Straps for Leather Bunker Boots (package of 2)	\$ 5.74	633-32
900	Brannock Sizing Device -- Men's Sizing	\$ 142.06	633-32
0098	Brannock Sizing Device -- Women's Sizing	\$ 142.06	633-32
903	DRYZ™ Inserts – Flat Bed (Trimmable) – Order One Size Lower than Boot Size. Whole Sizes Only – for Models 4132/4000/3009/3003	\$ 9.64	633-32
904	DRYZ™ Inserts -- Polyurethane Molded (Trimmable) Order One Size Lower than Boot Size Whole Sizes Only -- for Models 5006/3006/8000/6006/3050/3051/3060	\$ 13.48	633-32
901	Inserts (Trimmable) for Models 5006/3006/8000/6006/3050/3051/3060	\$ 10.53	633-32
902	Boot Jacks	\$ 12.11	633-32

PROPRIETARY ACCESSORIES

<i>Catalog Pages 47 and 48</i>			
20007	Toe Protector	\$ 23.63	633-32
BI-LK	Liner Keeper Straps	\$ 25.24	633-32
BI-ALK	Ankle Fit Straps	\$ 32.00	633-32
SR101	Studded Second Sole	\$ 45.75	633-32
SR201	Replacement Studs Kit (Includes Studs, Stud Extractor Tool, Stud Inserter Tool)	\$ 9.13	633-32

ADVANCED PROTECTIVE TRACKING (APT) SYSTEM

<i>Catalog Pages 4-7</i>			
SV-100	Level #1 Tracking – Barcode Label	Standard -- No Charge	
SV-200	Level #2 Tracking – CD with Program	\$ 89.76	633-99
SV-300	Level #3 Tracking • Retrofit kit allows departments to barcode existing boot stock (Level #2 program required). • Upon request, will also custom quote an in-department retrofit of existing stock. However, because of travel costs, such an approach is usually only cost effective for large departments. • Boots may be returned to our factory for retrofit barcoding. Call for quote and scheduling.	Call for Quote	633-99
SV-400	Level #4 Tracking Programs to allow other asset category tracking (truck, tools, etc.). Please call to describe your exact needs so we can provide a custom quote.	Call for Quote	633-99

NOTES

Special make-up sizes	\$ 60.00	633-99
-----------------------	----------	--------

OPTIONAL CERTIFICATIONS MUST BE REQUESTED AT TIME OF ORDER

- Special make up sizes subject to availability
- Special makeup sizes are not returnable
- No returns accepted without return authorization number
- Any return of perfect boots must be made within 60 days of invoice date
- Returned boots subject to restock charge at our discretion
- Warranty on boots is 1 year from date of purchase for manufacturing defects only.